


EXPLANATION

- Groundwater monitoring well
- ⊗ Destroyed groundwater monitoring well



Source: Figure modified from drawings provided by Parker Environmental Services (11/1/00) and Sonoma County Assessor's map.



GETTLER - RYAN Inc.
6747 Sierra Ct., Suite J
Dublin, CA 94568
(925) 551-7555

SITE PLAN
Food and Liquor #50
766 East Cotati Avenue
Cotati, California

PROJECT NUMBER
988171

REVIEWED BY

DATE
7/02

REVISED DATE